



SUMMARY

This is the final report by the Joint Accident Investigation Commission on the background and sequence of events leading to the foundering of the ro-ro passenger ferry ESTONIA shortly before 0200 hrs on 28 September 1994, and on the subsequent rescue operation *1*). The vessel was on a scheduled voyage from Tallinn to Stockholm with 989 people on board.

The report consists of four parts. The first part gives factual information on the accident, the rescue operation, and on the ESTONIA and her operation. It includes a summary of testimonies by the survivors. The second part presents background information, or associated facts related to the accident such as a short development history of the passenger ferry traffic in the Baltic and a review of bow door failures. The third part presents the results of the analysis and evaluation by the Commission of the accident and the rescue operation. This part incorporates short accounts of the separate investigations carried out on behalf of the Commission. The detailed research reports and copies of the most important documents are collected in a separate Supplement. The fourth part presents the conclusions based on the work carried out by and for the Commission.

1) If not otherwise stated all times in the report are given in Estonian time = UTC + 2 hrs.

Part I Factual information

[Chapter 1](#) gives facts on the most important events during the accident voyage, on the accident and very briefly on the rescue operation. [Chapter 2](#) describes the operating history of the vessel under the Finnish and Estonian flags with emphasis on the organisation of the operations and on the experience of the partners in the Tallinn - Stockholm traffic. Chapter 2 includes also general statistics on wave conditions in which the vessel had been sailing during her life.

[Chapter 3](#) is a general technical description of the ESTONIA focusing on the bow visor and ramp installations with detailed data on the design and construction of their locking systems, including the monitoring and control. The history of the vessel and in particular of the bow visor and the ramp installations with

regard to maintenance, modifications, damage and repairs is reviewed. Emergency and life-saving equipment and arrangements on board are outlined in 3.4. The vessel was built to comply with several international conventions which are listed, and the compliance was documented by certificates. The collision bulkhead compliance is dealt with in some detail. Certificates valid at the time of the accident are reviewed and the changes in wording of the most important certificate, the Passenger Ship Safety Certificate, which has to be renewed every year, are explained in detail.

[Chapter 4](#) describes the arrangement of operations on board and working routines, and gives summaries of qualifications of each deck officer and engineer on duty on the accident voyage. The safety organisation is outlined comprehensively.

[Chapter 5](#) is the second chapter directly dealing with the accident. The environmental conditions: wind, sea state, visibility and current during the accident voyage are defined on the basis of information obtained from meteorological institutes. The chapter concludes with an estimate of the ESTONIA's speed during the voyage. The speed profile has been constructed from the DGPS recording of the passenger ferry SILJA EUROPA's speed and is compared with observations of the actual speed.

[Chapter 6](#) is a summary of all statements made by the survivors and covers their experience from the time just prior to the accident until their rescue. The chapter is divided into two parts. The first part reports on statements made by the individual surviving crew members who were on duty during the accident, the second part summarises statements from both passengers and crew members off duty. Chapter 6 summarises as closely as possible the statements made by survivors, but specific details are not necessarily regarded as facts and may differ from the Commission's statements in other chapters.

[Chapter 7](#) begins with a general description of the rescue operation. This description first deals with international agreements on the safety of life at sea and then with the maritime search and rescue organisations of Estonia, Finland and Sweden as well as the co-operation between these countries.

The section on the ESTONIA's distress message and distress traffic describes the radio systems in use at the time of the accident and the coast radio stations which were keeping watch on distress and safety channels. The ESTONIA's entire distress traffic from 0122 hrs to 0130 hrs on 28 September 1994 has been transcribed on the basis of the tape recordings made.

The section on the search and rescue operations begins with a chronological list of the most important rescue actions during the first hours. After this, the operations undertaken by the vessels, helicopters and aircraft are described. The section concludes with data on victims and survivors.

Part 1 ends with [Chapter 8](#) which presents a detailed review of damage to the wreck, the ramp and the visor with their attachments, as observed visually during inspections with a

submarine Remotely Operated Vehicle (ROV), the diving operation and after the visor had been recovered and taken ashore. The damage is illustrated with several photographs. The extent of the diving operation is described and the divers' observations on the bridge and elsewhere in the wreck concerning e.g. victims are summarised. The state of the ESTONIA's life-saving equipment and emergency beacons (EPIRBs) when found after the accident is specified in 8.10 and 8.11, respectively.

Part 2 Associated facts

[Chapter 9](#) includes a general review of international co-operation and conventions within the framework of the International Maritime Organisation (IMO) and shortly describes the organisation of the Estonian, Finnish and Swedish Maritime Administrations. The role of the classification societies and their relationship with the ship owners, shipyards and the national administrations is described. The problems recognised in safety of ro-ro vessels before the ESTONIA disaster are pointed out with particular emphasis on the HERALD OF FREE ENTERPRISE accident in 1987.

[Chapter 10](#) is a brief commercial and technical history of the ro-ro ferry traffic in the Baltic. The chapter includes a list of passenger ferries put in traffic between south-west Finland and the Stockholm region in Sweden by the Silja Line and the Viking Line between 1959 and 1993, with the type of original bow enclosure defined.

Some of the incidents involving failure or part-failure of bow visor attachments of Finnish and Swedish ro-ro passenger ferries in the Baltic and the North Sea are summarised in [Chapter 11](#). The type and extent of damage is indicated in each case as well as the action taken after the accident. The incident of DIANA II in January 1993 in the southern Baltic has been investigated in more depth since she had a similar visor and attachment system design to the ESTONIA's.

Part 3 Analysis and evaluation

[Chapter 12](#) opens the analysis part of the report. It presents an overview of the separate investigations carried out for the Commission. These include analysis of wave loads on the visor based on model tests and numerical simulations, calculations of wave-induced motions and analysis of hydrostatic and hydrodynamic characteristics during flooding and sinking of the vessel. The chapter also summarises the various strength and metallurgic investigations carried out on parts recovered from the visor and ramp installations and calculations of the strength of the visor attachments.

[Chapter 13](#) is a main chapter in the report presenting the Commission's views on the course of events starting from the preparations for the accident passage and ending with the sinking of the ESTONIA. The chapter is based on an analysis of witness statements (Chapter 6) and all technical observations and data of which the main part is summarised in Chapters 3, 5, 8, 12 and 15.

The possible deficiencies existing in the visor and ramp closure before the accident voyage and their effect on the operation of the vessel are analysed in 13.2.3. Separation of the visor and development of the list and sinking are handled shortly in 13.2.5 and 13.2.6, respectively, while a more thorough treatment is given in 13.5 and 13.6.

Actions on the bridge in the light of information available to the bridge are analysed in 13.3, including an analysis of the effect of the ESTONIA's speed on passenger comfort and the accident. The time span considered is from the first signs of something being wrong at about the time of changing watch at 0100 hrs until the end of the distress traffic at 0130 hrs.

There were indicator lamps on the bridge showing locked or unlocked visor and ramp, respectively. Their indications and other advance alarms when the visor was becoming detached are analysed in 13.4.

[Chapter 14](#) describes the ownership and operating arrangements of the ESTONIA and analyses whether these may have been a contributing factor in the accident.

[Chapter 15](#) analyses the structural design of the visor and ramp attachments. The basis and procedures for design, manufacturing and approval are discussed. The estimated combined strength of the attachment system is compared to the estimated wave-induced loads and a probable load level and sequence of failure is presented.

[Chapter 16](#) is an analysis of the evacuation of the ship from the first early signs of the accident until the ship was abandoned by all who could. The basis for this chapter is witnesses' statements and findings by divers after the accident. The chapter deals with the alarms, activities and efforts by parts of the crew, activities by passengers, various obstacles to the evacuation and the role of rational and irrational human behaviour displayed.

[Chapter 17](#) is an analysis of the rescue operation on the basis of information and data summarised in Chapter 7. Chapter 17 considers first the distress traffic between the vessels and the coast stations. The action initiated by the distress calls on board the vessels in the vicinity of the ESTONIA and at the land-based rescue centres, in particular MRCC Turku, are evaluated in 17.3. The concluding part of the chapter deals with the action of vessels and helicopters during the rescue operation.

[Chapter 18](#) begins with a consideration how the practice common amongst the Finnish and Swedish Maritime Administrations of accepting in passenger ferries a forward-located bow ramp as an upper extension of the collision

bulkhead, contrary to the SOLAS regulations, may have developed. This chapter also evaluates the bow ramp arrangement of the ESTONIA in comparison with some other contemporary passenger ferries, and draws conclusions on the effect on the accident of non-compliance with the regulations.

The ESTONIA accident prompted an extensive investigation within the International Maritime Organisation (IMO) on all aspects of ro-ro passenger ships' safety. The work has led to improvement of existing safety regulations and development of detailed new ones of which a significant part has already come into force. The new safety regulations for passenger ferries developed by IMO after the accident are reviewed in [Chapter 19](#).

Part 4 Conclusions

Part 4 presents findings, conclusions and recommendations, in Chapters [20](#), [21](#) and [22](#), respectively.

