

Preliminary version

SUPPLEMENT

TO

THE FINAL REPORT ON THE CAPSIZING ON 28
SEPTEMBER 1994 IN THE BALTIC SEA OF THE
RO-RO PASSENGER VESSEL MV ESTONIA

Part I

The Joint Accident Investigation Commission
of
Estonia, Finland and Sweden

Preface

The Joint Accident Investigation Commission publishes in this Supplement the most important documents used in Commission's work. Large appendices of some research reports have been edited, but a list of appendices has been included.

This publication is a preliminary version. The final version will be published soon in one volume. Some documents will be added which due to editorial reasons had to be left out from this preliminary version.

CONTENTS

PART I

1 ADMINISTRATION

- 102 FIN Suomen Valtioneuvoston päätös Suomen edustajien nimeämisestä MV ESTONIAN onnettomuuden kansainväliseen tutkintakomissioon. Helsinki 29.9.1994.

Decision of the Council of State of Finland on the appointment of the members to the Joint Accident Investigation Commission of MV ESTONIA. Helsinki 29.9.1994.

- 103 SWE Regeringsbeslut K94/2393/2. Kommunikationsdepartementet. Uppdrag till Statens haverikommission att biträda i utredningsarbetet med anledning av passagerarfärjan Estonias förlisning. Stockholm 1994-09-28.

Government decision K 94/2393/2. Ministry of Transport and Communications. Direction to the Board of Accident Investigation to assist in the investigation of the capsizing of the passenger ferry MV ESTONIA. Stockholm 1994 - 09 - 28.

2 VESSEL

Ship design and construction

- 201 ENG Contract between Rederiaktiebolaget Sally, Mariehamn, Finland and Shipyard Jos. L. Meyer, Papenburg, Germany. Mariehamn 11 th September, 1979.
- 202 ENG Extracts from specification for building. Jos L. Meyer. Papenburg-Ems.
- 203 ENG Extracts from operation instructions for stern ramp, bow visor and bow ramp. Von Tell Ab. Gothenburg.
- 204 GER Handgeschriebene Festigkeitsberechnungen für die Bugvisier-Vesschlüsse der VIKING SALLY - ESTONIA.

Hand-written strength calculations for the VIKING SALLY-ESTONIA's bow visor locks.

- 205 ENG Extracts from Bureau Veritas Rules and Regulations for the construction and classification of Steel Vessels 1977. Paris.
- 206 ENG Bureau Veritas Note Documentaire BM2. Paris 5.4.1976.
- 207 GER Extrakt von Germanischer Lloyd Vorschriften für Klassifikation und Bau von stählernen Seeschiffen. Ausgabe 1978. Band 1. Hamburg.
- Extracts from Germanischer Lloyd Regulations for the classification and building of Steel Vessels. Version 1978. Part 1. Hamburg*
- 208 ENG Extracts from Lloyd's Register of Shipping Rules and Regulations for the Construction and Classification of Steel Ships 1976. London.
- 209 SWE Correspondence between Von Tell and the Finnish Maritime Administration about approval of the visor design in general.
- 210 ENG Von Tell telex to Bureau Veritas 18.3.1980 about visor attachment design loads and stresses.
- 211 ENG Extracts from notes made by the Bureau Veritas surveyor on the visor assembly drawing 590/1103 rex 6.
- 212 SWE M/S ESTONIA & M/S MARE BALTICUM - Utredning beträffande placering av kollisionsskott/förlig ramp. Nordström & Thulin. Stockholm 1994.
- M/S ESTONIA & M/S MARE BALTICUM - Investigation on placing of collision bulkhead/bow ramp. Nordström & Thulin. Stockholm 1994.*
- 213 FIN Letter 20.4.1977 from the Finnish Maritime Administration to the Wärtsilä Turku Shipyard on the approval of the bow ramp as an upper extension of the collision bulkhead in MV TURELLA.
- 214 SWE Correspondence between the Swedish Maritime Administration and

the Götaverken Öresund Shipyard 8.1.1979 on the application of the SOLAS regulations for an upper extension of the collision bulkhead in two passenger ferries for the Gotland traffic.

- 215 SWE Correspondence between the Swedish Maritime Administration and the Stena Line 20.3 - 26.3.1981 concerning MV KRON-PRINSESSAN VICTORIA.

Ship documents

- 216 ENG *Lehtola Kari*: VIKING SALLY - ESTONIA. SOLAS Passenger Ship Certificates and Inspection Certificates. Working paper 31.3.1996
- 217 ENG Selection of MV ESTONIA's certificates valid at the time of the accident.
- 218 ENG MV ESTONIA's classification certificates of 12.1.1993 for machinery and hull.
- 220 ENG Extracts from the Trim and Stability booklet of MV WASA KING. Ship Consulting Ltd Oy. Turku 20.1.1991

Surveys

- 221 FIN Section 45 of the Commercial Vessel Degree no. 23/1920.
SWE 12.12.1920.
- 222 SWE Decision of the Finnish Maritime Administration 1921 to approve certain classification societies for carrying out hull surveys.
- 223 ENG Protocol of MV ESTONIA's exercise Port State Control in Tallinn 27.9.1994.
- 224 ENG List of surveys carried out by Bureau Veritas on VIKING SALLY - ESTONIA.

Ship operation

- 225 ENG VIKING SALLY - SILJA STAR - WASA KING. Dockings and recorded damages to the bow 1981 - 1993. Memorandum 16.8.1995/FIN.

- 226 ENG Extracts from M/S ESTONIA Safety Manual.
- 228 ENG Safety round on board MV ESTONIA of the AB seaman on watch.
- 229 ENG Arrival times of MV ESTONIA and some other passenger ferries at the entrance of Stockholm Archipelago and in Stockholm 3.2.1993 - 26.9.1994. Extract from the log book at the Stockholm Pilot Station.
- 230 ENG List of maintenance and repair works on MV ESTONIA. April 1993 - August 1994. Nordström & Thulin AB. Stockholm.
- 231 SWE Extracts from docking specification and quotation 25.9.1992 for Wasa Line re MV WASA KING's docking 1993.

3 CREW

4 VOYAGE CONDITIONS

Weather

- 401 ENG Weather Conditions on the Northern Baltic at September 28, 1994. Estonian Meteorological and Hydrological Institute. Tallinn 1995.
- 402 ENG *Komulainen Marja-Leena: The Baltic Sea Storm on 28.9.1994. An investigation into the weather situation which developed in the northern Baltic at the time of the accident to m/s Estonia. Helsinki 1994.*
- 403 ENG The m/s ESTONIA accident. Weather conditions on September 27th and 28th 1994. Swedish Meteorological and Hydrological Institute. Norrköping 1995.

Wave conditions

- 405 ENG *Kahma Kimmo - Pettersson Heidi - Myrberg Kai - Jokinen Hannu: Estimated Wave Conditions and Currents during the last Voyage of M/S Estonia. Finnish Institute of Marine Research. Helsinki 1996.*

406 FIN Merkitsevän aallonkorkeuden todennäköisyydet M/V ESTONIAN käyttämällä reiteillä. Merentutkimuslaitos. Helsinki 11.4.1997.

Significant wave height probabilities on the routes operated by MV ESTONIA. Finnish Institute of Marine Research. Helsinki 11.4.1997.

407 ENG *Kahma Kimmo - Pettersson Heidi: Wave Height - Wave Period Distribution from the Northern Baltic Proper. Finnish Institute of Marine Research. Helsinki 1996.*

Seakeeping

408 ENG *Karppinen Tuomo - Rintala Sakari - Rantanen Antti: MV ESTONIA Accident Investigation. Numerical predictions of wave loads on the bow visor. Technical Report VALC106. VTT Manufacturing Technology. Espoo 1995.*

409 ENG *Huss Mikael: Wave loads on visor attachments. MV ESTONIA Accident Investigation. Internal report 1995 - 1997.*

410 ENG *Trägårdh Peter: Model test with M/S ESTONIA. Sea loads on bow visor and yawing behaviour due to heel. SSPA Maritime Consulting. Report 7524. Gothenburg 1995.*

411 ENG *Sundell Tom: MV ESTONIA Accident Investigation. Forces acting on the bow visor due to stationary flow. Technical Report VALC55. VTT Manufacturing Technology. Espoo 1995.*

412 ENG *Karppinen Tuomo - Rantanen Antti: MV ESTONIA Accident Investigation. Numerical predictions of wave-induced motions. Technical Report VALC53. VTT Manufacturing Technology. Espoo 1995.*

413 ENG *Karppinen Tuomo: MV ESTONIA Accident Investigation. Effect of speed on the visor loads. Working paper 29.10.1996.*

PART II

5 OTHER INVESTIGATIONS

General observations after the accident

- 501 FIN M/S Estonian hylyn ympäristöstä laadittujen merenpohjakarttojen selitys. Merivoimien Tutkimuslaitos. Helsinki 28.3.1995.
- 502 SWE Rapport angående de tekniska och legala förutsättningarna att återfinna och omhänderta omkomna från färjan Estonia. Sjöfartsverket. 1994.
- Report concerning technical and legal conditions to find and take care of victims from the ferry Estonia. Swedish Maritime Administration.*
- 503 ENG *Rockwater A/S: Condition Survey of the Vessel "Estonia" for the Swedish National Maritime Administration. Survey Report.*

The vessel

- 504 ENG *Karppinen Tuomo - Rantanen Antti: MV Estonia Accident Investigation. Stability calculations. Technical Report VALC177. VTT Manufacturing Technology. Espoo 1996.*
- 505 ENG *Karppinen Tuomo - Rintala Sakari: MV Estonia Accident Investigation. Stability calculations with water on the tank deck. Research Report VAL313-7331. VTT Manufacturing Technology. Espoo 1997.*
- 506 ENG *Ingerma A. - Strizhak V.: The Strength Studies for the Locking Devices of the Bow Visor of M/V ESTONIA. Estonian Maritime Academy & Tallinn Technical University. Tallinn 1997.*
- 507 ENG *Metsaveer Jaan: MV ESTONIA Accident Investigation. Calculation of Load-Carrying Capacity of the Bow Visor Locks. Tallinn Technical University. Tallinn 1996.*
- 508 ENG *Katajamäki Kai: MV Estonia Accident Investigation. Strength investigation of the visor side locking device, numerical*

- calculations. Technical report VALC-246. VTT Manufacturing Technology. Espoo 1996.
- 509 ENG *Häkki-Rönholm Eeva*: Investigation of paint systems from MV Estonia Visor Bottom Lock. Research Report No. RTE57243/96. VTT Building Technology. Espoo 1996.
- 510 ENG *Ingerma A. - Strizhak V.*: An Analysis of the Reasons of the Failure of the Locking Devices of MV Estonia. Estonian Maritime Academy. Tallinn Technical University. Tallinn 1996.
- 511 ENG *Rahka Klaus*: MV Estonia. Visor Damage and Visor Attachment Strength Investigations at VTT. Report VALB243. VTT Manufacturing Technology. Espoo 1997.
- 512 ENG *Airaksinen Jukka*: MV ESTONIA. Accident Investigation. Strength Investigation of the Visor Hinge, Numerical Calculations. Technical Report VALC312. VTT Manufacturing Technology. Espoo 1997.
- 513 FIN *Kleimola Matti*: Laskelmat ESTONIAN keulavisiirin lukituslaitteiden kuormituksista. Espoo 1997.
- Kleimola Matti: Calculations of the loadings on MV ESTONIA's bow visor locking devices. Espoo 1997*
- 514 FIN *Kleimola Matti*: Laskelmat ESTONIAN keulavisiirin lukituslaitteiden kuormituksista (2. raportti). Espoo 1997.
- Kleimola Matti: Calculations of the loadings on MV ESTONIA's bow visor locking devices. 2nd Report. Espoo 1997.*
- 515 ENG *Niemi Erkki*: Upper Bound Estimation on the Ultimate Load Capacity of the Atlantic Lock. Lappeenranta University of Technology. Lappeenranta 1997.
- 516 ENG *Nilsson Fred - Öberg Hans*: Strength and failure assessments of parts from MV ESTONIA. Royal Institute of Technology. Stockholm 1996.
- 517 ENG *Pettersson Kjell - Söderholm P-O - Lange Nils*: Metallographic and fractographic examinations of samples from MV Estonia. Royal Institute of Technology. Stockholm 1995.

- 518 ENG *Pettersson Kjell - Söderholm P-O*: Notes from metallographic and fractographic examinations of samples from MV Estonia. Royal Institute of Technology. Stockholm 1996.
- 519 ENG *Öberg Hans*: Investigation of deformations and related loads, applied to the lug of the visor bottom lock of MV ESTONIA. Royal Institute of Technology. Stockholm 1996.
- 520 ENG MS ESTONIA Bow Visor. Inspection Report of PS-side Hydr. Lifting Cylinder. MacGREGOR (FIN) Oy. Piikkiö 1995.

Ship operations

- 521 ENG *Larjo Kari*: ESTONIA's shedule, ETA-PILOT and NaviSailor 2100. 15.10.1996.
- 522 ENG *Huss Mikael*: Simulation of the capsize. MV ESTONIA Accident Investigation. Internal report 1995 - 1997.
- 523 ENG *Rintala Sakari - Karppinen Tuomo*: MV ESTONIA Accident Investigation. Numerical predictions of the water inflow to the car deck. Technical Report VALC174. VTT Manufacturing Technology. Espoo 1996.

Operating history

- 524 ENG *Wermelin Hans*: M/S Estonia, a ship emanating from The Baltic Phenomenon. An historical overview made by *ADC Support AB*. Stockholm 1995.

Damages to bow of other vessels

- 525 ENG *Laur Uno*: Report. Damage to bow visor locking devices of passenger car ferry "DIANA II" in January, 1993, and preliminary conclusion i.r.o. the loss of the bow visor of m.v. "ESTONIA" on September 28th, 1994. Tallinn 1994.
- 526 ENG *Lehtola Kari*: Damage to the Bow of the SILJA EUROPA at the Time of the Accident Involving the ESTONIA 28.9.1994.

6 EVACUATION AND RESCUE

- 602 FIN Suuronnettomuuden pelastussuunnitelma Saaristomeren meripelastusalueella. 18.6.1991.
Rescue Plan for Major Maritime Accident in the Archipelago Sea Maritime SRR. 18.6.1991.
- 603 SWE *ARCC Arlanda: Bakgrund avtal enl Räddningstjänstlagen, larmtider och erfarenheter.*
- 604 ENG *Penttilä Antti - Ranta Helena: Medicolegal Examination and Identification of Victims of M/S Estonia Mass Disaster. Department of Forensic Medicine, University of Helsinki - The Finnish DVI Team - Ministry of Justice. Helsinki 1996.*